

Infoblatt zu Drehmomenten von Deckelschrauben

Maximale Drehmomente



	AS060 bis AS104	3,0Nm		AD080 bis AD104	3,0Nm
	AS120 bis AS 324	4,0Nm		ASD20 bis AD 324	4,0Nm
	AF080 bis AF104	3,0Nm		AH100 bis AH104	3,0Nm
	AF120 bis AF324	4,0Nm		AH120 bis AH244	4,0Nm
	AC052 bis AC074	2,5Nm		EK/F081 bis EK/F083	2,5Nm
	AC090 bis AC302	3,0Nm		EK/F121 bis EK/F162	3,5Nm
				EKT/F082 bis EKT/F083	2,5Nm
	AK060 bis AK084	2,5Nm		AR080	2,5Nm
	AK120 bis AK312	3,5Nm		AR100 bis AR160	3,5Nm
	AP082 bis AP102	2,5Nm		ACL092 bis ACL132	3,0Nm
	AP120 bis AP162	3,0Nm			
	ADO090 bis ADO172	3,0Nm		KE160 bis KE242	4,0Nm
	ADF090 bis ADF172	3,0Nm		KVF120 bis KVF324	4,0Nm
				KVE120 bis KVE324	4,0Nm
				KTE160 bis KTE162	4,0/3,5Nm
	ATF100 bis AT100	3,0Nm		PT080 bis PT104	2,0Nm
	AT160 bis AT162	4,0/3,5Nm		PT120 bis PT400	2,5Nm
	PK081 bis PK084	2,0Nm		PD120 bis PD202	2,5Nm
	PK121 bis PK411	2,5Nm		PD120 FE bis PD202 FE	2,5Nm
	TA080 bis TA162	1,0Nm		SC090 bis SC172	1,0Nm
	TAF080 bis TAF242	1,0Nm			
	TAH162 bis TAH242	1,0Nm			
	TBA060 bis TBA162	1,0Nm		TP090 bis TP172	1,0Nm
	TD080 bis TD160	1,0Nm		Set DF/DK/PG 80 bis 130 P1/P2	1,0Nm
	HCF080 bis HC100	2,5Nm		PCV 7 und 10	3,0Nm
				PCD 7 und 10	3,0Nm